



# Corrective Action Notice

**School :** BUSHNELL WAY EL  
**Cost Center :** 0001267101  
**Address :** 5507 BUSHNELL WAY  
LOS ANGELES, CA90042

**Site Administrator :**  
**Complex Project Manager :** Ignacio Chavez

**Inspection Date :** Jan 13, 2023  
**Inspector :** Logan, Sean

**Inspection Type :** Routine Safe School Inspection

Priority	Due Date	Deficiency#	Category	Corrective Action	Comments	Location	Resp. Party	Certify
Level 1	Jan 13, 2023	36228196	Lead Management	Repair areas of peeling or otherwise deteriorated paint surfaces and clean up paint debris. If necessary, submit a service request to the Maintenance and Operations Maximo Kiosk at <a href="https://facapps.lausd.net/oehs/">https://facapps.lausd.net/oehs/</a> .		Exterior of bungalow buildings located on the lower yard	Facilities	
Level 1	Jan 13, 2023	36228125	Chemical Safety	Do not use chemicals unless approved for District use by OEHS. Refer to the OEHS website at <a href="https://achieve.lausd.net/oehschemeval">https://achieve.lausd.net/oehschemeval</a> (see Product Review) or contact OEHS at (213) 241-3199 for assistance.		Room K2; Room 19; & Room 11	School	
Level 2	Feb 12, 2023	36228113	Emergency Procedures (Integrated Safe School Plan)	Remove all materials and objects stored on top of cabinets or upper shelves unless such objects are fastened to the shelf or otherwise restrained from falling.		Room 14 & Multi-Purpose Room	School	
Level 2	Feb 12, 2023	36228123	Indoor Environment	Correct all unresolved water damage. If necessary, submit a service request to the Maintenance and Operations Maximo Kiosk at <a href="https://facapps.lausd.net/oehs/">https://facapps.lausd.net/oehs/</a> .		Room 21; Room 16; Nurse's Office; Auditorium; & Main building second floor ceiling	Facilities	
Level 2	Feb 12, 2023	36228190	Facilities and Equipment Maintenance	Ensure asphalt and other paved areas are in good condition (e.g., free of significant cracks, holes, standing water). If necessary, submit a service request to the Maintenance and Operations Maximo Kiosk at <a href="https://facapps.lausd.net/oehs/">https://facapps.lausd.net/oehs/</a> .		Perimeter fencing & Transformer enclosure adjacent to the main building	Facilities	

Priority	Due Date	Deficiency#	Category	Corrective Action	Comments	Location	Resp. Party	Certify
Level 2	Feb 12, 2023	36228118	Facilities and Equipment Maintenance	Repair/replace damaged or missing ceiling tile(s). Consult the Asbestos Management Plan prior to repair. If necessary, submit a service request to the Maintenance and Operations Maximo Kiosk at <a href="https://facapps.lausd.net/oehs/">https://facapps.lausd.net/oehs/</a> .		Room 21; Room 16; Room 11 & Main building North Stairwell	Facilities	
Level 2	Feb 12, 2023	36228144	Facilities and Equipment Maintenance	Ensure campus grounds and equipment are maintained in good repair. If necessary, submit a service request to the Maintenance and Operations Maximo Kiosk at <a href="https://facapps.lausd.net/oehs/">https://facapps.lausd.net/oehs/</a> .	The elevator is non-operational.	Library Building	Facilities	
Level 2	Feb 12, 2023	36228180	Facilities and Equipment Maintenance	Ensure campus grounds and equipment are maintained in good repair. If necessary, submit a service request to the Maintenance and Operations Maximo Kiosk at <a href="https://facapps.lausd.net/oehs/">https://facapps.lausd.net/oehs/</a> .	The emergency bin has indications of water damage.	Emergency Bin	Facilities	
Level 2	Feb 12, 2023	36228103	Facilities and Equipment Maintenance	Ensure all areas within the school have adequate indoor lighting. If necessary, submit a service request to the Maintenance and Operations Maximo Kiosk at <a href="https://facapps.lausd.net/oehs/">https://facapps.lausd.net/oehs/</a> .		Multi-Purpose Room	Facilities	
Level 3	Apr 13, 2023	36228136	Fire/Life Safety	Post signs in a conspicuous place near the main exit doorway of assembly rooms indicating maximum occupant load and usage.		Library	Facilities	