



Corrective Action Notice

School : KING JR EL
Cost Center : 0001653401
Address : 3989 S HOBART BLVD
 LOS ANGELES, CA90062

Site Administrator :
Complex Project Manager : Lisa Marine

Inspection Date : Jan 12, 2023
Inspector : Logan, Sean

Inspection Type : Routine Safe School Inspection

Priority	Due Date	Deficiency#	Category	Corrective Action	Comments	Location	Resp. Party	Certify
Level 1	Jan 12, 2023	36225086	Chemical Safety	Do not use chemicals unless approved for District use by OEHS. Refer to the OEHS website at https://achieve.lausd.net/oehschemeval (see Product Review) or contact OEHS at (213) 241-3199 for assistance.		Underneath the sink, Room 46	School	
Level 1	Jan 12, 2023	36225067	Fire/Life Safety	Maintain a minimum 3-foot clearance around fire extinguishers, fire hoses, pull stations and sprinkler control valves.	Fire Extinguisher adjacent to Librarian's Desk.	Library	School	
Level 1	Jan 12, 2023	36225114	Lead Management	Repair areas of peeling or otherwise deteriorated paint surfaces and clean up paint debris. If necessary, submit a service request to the Maintenance and Operations Maximo Kiosk at https://facapps.lausd.net/oehs/ .	All the window sills of the main building have peeling paint.	MAIN BLDG - KING JR ES, Main building	Facilities	
Level 1	Jan 12, 2023	36225033	Fire/Life Safety	Maintain exit pathways free of obstructions to ensure safe egress.	Emergency window obstructed.	Room 12B; Room 5; Room 39; Room 46; Room 47; Library; & Main office	School	
Level 2	Feb 11, 2023	36225079	Fire/Life Safety	Ensure automatic sprinkler systems are tested annually. Note testing date in the Fire Log Book.			Facilities	
Level 2	Feb 11, 2023	36225060	Facilities and Equipment Maintenance	Repair/replace damaged or missing ceiling tile(s). Consult the Asbestos Management Plan prior to repair. If necessary, submit a service request to the Maintenance and Operations Maximo Kiosk at https://facapps.lausd.net/oehs/ .		Room 14 & Room 30	Facilities	

Priority	Due Date	Deficiency#	Category	Corrective Action	Comments	Location	Resp. Party	Certify
Level 2	Feb 11, 2023	36225104	Facilities and Equipment Maintenance	Ensure campus grounds and equipment are maintained in good repair. If necessary, submit a service request to the Maintenance and Operations Maximo Kiosk at https://facapps.lausd.net/oehs/ .	There is a hole along the west wall of the Lunch Shelter.	Lunch Shelter	Facilities	
Level 2	Feb 11, 2023	36225121	Facilities and Equipment Maintenance	Ensure playground equipment and matting complies with American Society for Testing and Materials (ASTM) standards and Consumer Products Safety Commission (CPSC) guidelines.	The slide on the central yard playground apparatus is damaged.	5-12 year old play structure	Facilities	
Level 2	Feb 11, 2023	36225135	Facilities and Equipment Maintenance	Repair/replace damaged or deteriorated playground surfacing materials. If necessary, submit a service request to the Maintenance and Operations Maximo Kiosk at https://facapps.lausd.net/oehs/ .		5-12 year old play structure	Facilities	
Level 2	Feb 11, 2023	36225090	Indoor Environment	Correct all unresolved water damage. If necessary, submit a service request to the Maintenance and Operations Maximo Kiosk at https://facapps.lausd.net/oehs/ .		Room 14	Facilities	
Level 2	Feb 11, 2023	36225013	Injury and Illness Prevention	Remove household appliances (e.g., toaster/oven, microwave oven, refrigerator, coffee machine, and heater) or other unauthorized electrical appliances from classrooms pursuant to Bulletin 6436.	Microwave in room 15 cabinet.	Room 15	School	
Level 2	Feb 11, 2023	36225083	Pest Management	Ensure air curtains and fly fans are turned on during food preparation and service.	The kitchen does not have a fly fan.	Kitchen	Food Services	
Level 2	Feb 11, 2023	36225081	Fire/Life Safety	Maintain a minimum 18-inch clearance between overhead sprinklers and materials below. In non-sprinklered areas, a minimum of 2-foot clearance must be maintained.		Kitchen	School	
Level 2	Feb 11, 2023	36225047	Emergency Procedures (Integrated Safe School Plan)	Remove all materials and objects stored on top of cabinets or upper shelves unless such objects are fastened to the shelf or otherwise restrained from falling.		Room 5; Room 14; Room 15; Room 29; Room 30; Room 39; & Room 52	School	
Level 2	Feb 11, 2023	36225053	Fire/Life Safety	Remove combustible materials (e.g. paper decorations, hanging mobiles) from exit doors, ceilings, electrical panels, light fixtures, fire sprinklers and heaters.		Room 5; Room 40; Room 52; & Library	School	
Level 3	Apr 12, 2023	36225100	Fire/Life Safety	Post signs in a conspicuous place near the main exit doorway of assembly rooms indicating maximum occupant load and usage.		Auditorium	Facilities	

Priority	Due Date	Deficiency#	Category	Corrective Action	Comments	Location	Resp. Party	Certify
Level 3	Apr 12, 2023	36225106	Asbestos Management	Ensure a 3-Year Asbestos Re-Inspection is conducted by the Facilities Environmental Technical Unit (FETU) and results are included in the school Asbestos Management Plan. For assistance, contact FETU at (213) 745-1450.		Main office	Facilities	

List of Open Deficiencies in this site

Priority	Due Date	Deficiency#	Category	Corrective Action	Comments	Location	Resp. Party	Certify
Level 1	Feb 12, 2016	28339465	Fire/Life Safety	Maintain a minimum 3-foot clearance around fire extinguishers, fire hoses, pull stations and sprinkler control valves.	Maintain a minimum 3-foot clearance around fire extinguishers, fire hoses, pull stations and sprinkler control valves.	Kitchen	School	
Level 2	Mar 13, 2016	28339492	Fire/Life Safety	Conduct and document monthly visual inspection of portable fire extinguishers. Note inspection date on the service tag and the Fire Log Book.	Note the inspection date and sign the service tag on the fire extinguisher. Update Tab 3 in the M&O Fire Log book.	Room 8 Computer Lab	School	
Level 2	Mar 13, 2016	28339493	Fire/Life Safety	Conduct and document monthly visual inspection of portable fire extinguishers. Note inspection date on the service tag and the Fire Log Book.	Note the inspection date and sign the service tag on the fire extinguisher. Update Tab 3 in the M&O Fire Log book.	6534_King Jr ES_Room 15	School	
Level 2	Mar 13, 2016	28339502	Fire/Life Safety	Conduct and document monthly inspections of fire alarms in the Fire Log Book to ensure they are in good working order. Ensure a different pull station is tested each month.	Conduct and document monthly inspections of fire alarms in the Fire Log Book to ensure they are in good working order. Ensure a different pull station is tested each month.		School	
Level 3	May 12, 2016	28339498	Injury and Illness Prevention	Conduct and document semi-annual safety inspections pursuant to Injury and Illness Prevention Program (IIPP). Maintain inspection records for at least 3 years.	Conduct and document semi-annual safety inspections pursuant to Injury and Illness Prevention Program (IIPP). Maintain inspection records for at least 3 years.		School	
Level 3	May 12, 2016	28339501	Chemical Safety	Provide all employees with annual Hazard Communication training on hazardous chemicals used in their respective work areas. Employees must be retrained when new hazards are introduced into the workplace.	Provide employees with annual Hazard Communication training on hazardous chemicals used in their respective work areas. Employees must be retrained when new hazards are introduced into the workplace.		School	

List of Open Deficiencies in this site

Priority	Due Date	Deficiency#	Category	Corrective Action	Comments	Location	Resp. Party	Certify
Level 3	May 12, 2016	28339499	Injury and Illness Prevention	Establish a School Safety Committee that meets at least quarterly and documents meeting minutes. Responsibilities include: review inspection findings, alleged hazardous conditions and incident reports to identify safety issues and prevent recurrence.	Establish a School Safety Committee that meets at least quarterly and documents meeting minutes. Responsibilities include: review inspection findings, alleged hazardous conditions and incident reports to identify safety issues and prevent recurrence.		School	
Level 1	Oct 6, 2017	28349738	Lead Management	Repair areas of peeling or otherwise deteriorated paint surfaces and clean up paint debris. If necessary, submit a service request to the Maintenance and Operations Maximo Kiosk at https://facapps.lausd.net/oehs/ .	As of 10.06.2017, peeling paint was still observed on bookshelves.	6534_King Jr ES_Room 14	Facilities	
Level 1	Oct 6, 2017	28349729	Fire/Life Safety	Maintain exit pathways free of obstructions to ensure safe egress.	The tables are bolted down, however there is enough clearance to be able to use the emergency exit windows. The turn dial is not obstructed by any furniture or other materials.	Room 8 Computer Lab	School	
Level 1	Oct 6, 2017	28349725	Fire/Life Safety	Maintain a minimum 3-foot clearance around fire extinguishers, fire hoses, pull stations and sprinkler control valves.	As of 10.06.2017, the shelving unit is still located within three feet of sprinkler control valves.	Kitchen	School	
Level 3	Jan 4, 2018	28349735	Injury and Illness Prevention	Prepare and implement an Injury and Illness Prevention Program (IIPP) using the OEHS "IIPP Template," and update at least annually in accordance with BUL-3772.3. For assistance, contact OEHS at (213) 241-3199.	OEHS found two years (2016/2017 and 2017/2018) IIPP plans.	Auditorium	School	
Level 3	Jan 4, 2018	28349721	Chemical Safety	Provide all employees with annual Hazard Communication training on hazardous chemicals used in their respective work areas. Employees must be retrained when new hazards are introduced into the workplace.	As of 10.06.2017, the school has not provided Hazard Communications training to staff. OEHS advised staff and provided the pdf and PowerPoint to site administration. Site administration will schedule training.		School	
Level 3	Jan 4, 2018	28349734	Injury and Illness Prevention	Conduct and document semi-annual safety inspections pursuant to Injury and Illness Prevention Program (IIPP). Maintain inspection records for at least 3 years.	OEHS discussed conducting the semi-annual safety inspections with site administration. They are to keep records with the updated IIPP binder for each year.	Auditorium	School	

List of Open Deficiencies in this site

Priority	Due Date	Deficiency#	Category	Corrective Action	Comments	Location	Resp. Party	Certify
Level 2	Sep 7, 2022	33429004	Fire/Life Safety	Provide at least one security grill with "emergency breakaway" capacity for classrooms equipped with security grills. The window with the breakaway grill must be openable and clearly identified as an emergency exit. In classrooms with only one exit door, the breakaway grill must be located furthest from the exit door. If necessary, submit a service request to the Maintenance and Operations Maximo Kiosk at https://facapps.lausd.net/oehs/ .	None of the classrooms on the 1st or 2nd floor of the charter building have releasable grills.	New Heights Charter Building	Facilities	