



Corrective Action Notice

School : PANORAMA SH
Cost Center : 0001861001
Address : 8015 VAN NUYS BLVD
 PANORAMA CITY, CA91402

Site Administrator : GIUSEPPE NARDULLI
Complex Project Manager : Richard Craig

Inspection Date : Feb 21, 2023
Inspector : Oguine, Debra
Inspection Type : Routine Safe School Inspection

Priority	Due Date	Deficiency#	Category	Corrective Action	Comments	Location	Resp. Party	Certify
Level 1	Feb 21, 2023	36375370	Fire/Life Safety	Maintain exit pathways free of obstructions to ensure safe egress.	Relocate all objects blocking doors.	Room C202; Room A208	School	
Level 1	Feb 21, 2023	36375418	Chemical Safety	Do not use chemicals unless approved for District use by OEHS. Refer to the OEHS website at https://achieve.lausd.net/oehschemeval (see Product Review) or contact OEHS at (213) 241-3199 for assistance.	Remove plugged in air freshener from classroom.	Room C401	School	
Level 1	Feb 21, 2023	36375458	Chemical Safety	Do not use chemicals unless approved for District use by OEHS. Refer to the OEHS website at https://achieve.lausd.net/oehschemeval (see Product Review) or contact OEHS at (213) 241-3199 for assistance.	Remove Lysol aerosol from classroom.	Room A202	School	
Level 1	Feb 21, 2023	36375343	Injury and Illness Prevention	Ensure proper guarding is provided and maintained on all equipment to prevent injury to operators.	Replace missing paper cutter safety latch.	Room C222	Facilities	
Level 2	Mar 23, 2023	36375508	Facilities and Equipment Maintenance	Repair/replace damaged or missing ceiling tile(s). Consult the Asbestos Management Plan prior to repair. If necessary, submit a service request to the Maintenance and Operations Maximo Kiosk at https://facapps.lausd.net/oehs/ .		A212; B403 Hallway; A405 Hallway; Girls' Basketball Locker Room; Main Office Hopper Room	Facilities	
Level 2	Mar 23, 2023	36375513	Facilities and Equipment Maintenance	Ensure campus grounds and equipment are maintained in good repair. If necessary, submit a service request to the Maintenance and Operations Maximo Kiosk at https://facapps.lausd.net/oehs/ .	Remove/repair table and chair with splintered wood surfaces to prevent injury for students and staff.	Hallway by Fitness Room	Facilities	

Priority	Due Date	Deficiency#	Category	Corrective Action	Comments	Location	Resp. Party	Certify
Level 2	Mar 23, 2023	36375400	Facilities and Equipment Maintenance	Ensure campus grounds and equipment are maintained in good repair. If necessary, submit a service request to the Maintenance and Operations Maximo Kiosk at https://facapps.lausd.net/oehs/ .	Replace missing baseboard.	Room A202	Facilities	
Level 2	Mar 23, 2023	36375347	Emergency Procedures (Integrated Safe School Plan)	Remove all materials and objects stored on top of cabinets or upper shelves unless such objects are fastened to the shelf or otherwise restrained from falling.		Room C222 Storage Room; Room A212 Storage Room; Room A310A	School	
Level 2	Mar 23, 2023	36375477	Fire/Life Safety	Remove combustible materials (e.g. paper decorations, hanging mobiles) from exit doors, ceilings, electrical panels, light fixtures, fire sprinklers and heaters.	Remove combustibles/paper decorations covering entire door surface.	Room B305; Room B418	School	
Level 2	Mar 23, 2023	36375364	Facilities and Equipment Maintenance	Ensure campus grounds and equipment are maintained in good repair. If necessary, submit a service request to the Maintenance and Operations Maximo Kiosk at https://facapps.lausd.net/oehs/ .	Replace missing base for fire sprinkler head.	Hallway by Room C202; Hallway by Room B210; Hallway by Room B206	Facilities	
Level 2	Mar 23, 2023	36375383	Facilities and Equipment Maintenance	Ensure campus grounds and equipment are maintained in good repair. If necessary, submit a service request to the Maintenance and Operations Maximo Kiosk at https://facapps.lausd.net/oehs/ .	Replace missing base for drinking fountain pipe fixture.	Hallway by Room A212	Facilities	
Level 3	May 23, 2023	36377440	Fire/Life Safety	Post signs in a conspicuous place near the main exit doorway of assembly rooms indicating maximum occupant load and usage.	Post maximum occupancy load signs.	Auditorium; Gym; Student Dining; Small Gym; Library	Facilities	
Level 3	May 22, 2023	36375333	Asbestos Management	Ensure 6-Month Visual Surveillance is conducted by the Facilities Environmental Technical Unit (FETU) and results are included in the school Asbestos Management Plan. For assistance, contact FETU at (213) 745-1450.	Need current 6-Month Visual Surveillance report in the Asbestos Management Plan. The last report observed was completed in June 2022.	Main Office	Facilities	
Level 3	May 22, 2023	36375313	Injury and Illness Prevention	Conduct and document semi-annual safety inspections pursuant to Injury and Illness Prevention Program (IIPP). Maintain inspection records for at least 3 years.	Use IIPP Attachment "E" to document semi-annual inspections.	Main Office	School	