



Corrective Action Notice

School : PARKS LC
Cost Center : 0001357601
Address : 8855 NOBLE AVE
NORTH HILLS, CA91343

Site Administrator : MIRIAM KING
Complex Project Manager : Mauricio Pinto

Inspection Date : Jan 23, 2023
Inspector : Karibyants, George

Inspection Type : Routine Safe School Inspection

Priority	Due Date	Deficiency#	Category	Corrective Action	Comments	Location	Resp. Party	Certify
Level 1	Jan 23, 2023	36268820	Fire/Life Safety	Maintain exit pathways free of obstructions to ensure safe egress.	Remove all items that are blocking the exits.	Electrical Room in MPR; Book Room on the 2nd floor in the hallway between buildings A & C	School	
Level 2	Feb 22, 2023	36268807	Injury and Illness Prevention	Remove household appliances (e.g., toaster/oven, microwave oven, refrigerator, coffee machine, and heater) or other unauthorized electrical appliances from classrooms pursuant to Bulletin 6436.	Remove microwave from classroom.	Room 44	School	
Level 2	Feb 22, 2023	36268805	Facilities and Equipment Maintenance	Conduct and document weekly testing of all special access lifts (e.g., wheelchair lifts, auditorium stage lifts and swimming pool immersion lifts).	Replace the lights that are non-operable.	MULTI-PURPOSE BLDG, MPR	School	
Level 2	Feb 22, 2023	36268845	Facilities and Equipment Maintenance	Ensure campus grounds and equipment are maintained in good repair. If necessary, submit a service request to the Maintenance and Operations Maximo Kiosk at https://facapps.lausd.net/oehs/ .	Submit a service call for the elevator repairs.	Building A	Facilities	
Level 2	Feb 22, 2023	36268823	Pest Management	Mitigate insect infestation (e.g., ants, cockroaches, termites). If necessary, submit a service request to the Maintenance and Operations Maximo Kiosk at https://facapps.lausd.net/oehs/ .		Room 6	Facilities	

Priority	Due Date	Deficiency#	Category	Corrective Action	Comments	Location	Resp. Party	Certify
Level 3	Apr 23, 2023	36268827	Facilities and Equipment Maintenance	Post valid operating permit near air compressor, air pressure tank, elevator, boiler, or other equipment subject to Occupational Safety and Health Administration (OSHA) permitting.	Ensure to post the most recent permit in the elevator.	Elevator by the Main Office; ADA Lift in MPR	Facilities	
Level 3	Apr 23, 2023	36268837	Pest Management	Maintain a copy of the District's Integrated Pest Management (IPM) program in the main office. Contact Pest Management at (213) 745-1435 to obtain a copy.	Ensure pest management visits/inspections are documented in the sign-in sheet of the Integrated Pest Management Plan.		School	
Level 3	Apr 23, 2023	36268841	Asbestos Management	Ensure 6-Month Visual Surveillance is conducted by the Facilities Environmental Technical Unit (FETU) and results are included in the school Asbestos Management Plan. For assistance, contact FETU at (213) 745-1450.			Facilities	
Level 3	Apr 23, 2023	36268840	Asbestos Management	Ensure a 3-Year Asbestos Re-Inspection is conducted by the Facilities Environmental Technical Unit (FETU) and results are included in the school Asbestos Management Plan. For assistance, contact FETU at (213) 745-1450.			Facilities	
Level 3	Apr 23, 2023	36268830	Injury and Illness Prevention	Conduct and document semi-annual safety inspections pursuant to Injury and Illness Prevention Program (IIPP). Maintain inspection records for at least 3 years.			School	